
TOYOTA VANGUARD Stock ID 210542

Registration Year: 2009 Manufacture Year: 2009

Vehicle Specifications

| Model: | | Chassis No: | ACA38-5142497 | Grade: | | Fuel: | Petrol |
|----------------|------|-----------------|---------------|--------------------|-------------------|-----------|--------|
| Engine: | 2AZ | Drive Train: | 4WD | Dimensions: | 14 M ³ | Shape: | SUV |
| Engine No: | 2023 | Transmission: | AT | Mileage: | 90056 | Capacity: | 2400cc |
| Ext. Color: | | Weight (kg): | | Seats: | 7 | Color: | |
| Certification: | | Classification: | | Exterior: | BLACK | Interior: | GRAY |

Vehicle images



Vehicle Options

| Pwr Steering | Yes | Pwr Wind | Yes | Pwr Mirrors | Yes | Center Lock | Yes | Air Cond | Yes |
|----------------|-----|-------------------|-----|-----------------|-----|------------------------|-----|---------------|-----|
| Reverse Camera | Yes | Pwr Slide Door | | Easy Closer | | Cruise Control | | ABS | |
| Air Bag | Yes | Fog Lamps | Yes | HID Head Lamps | | LED Head Lamps | | Spare Key | |
| Remote Key | | Push Start | Yes | Seat Heater | | Pwr Seat | | Leather Seat | |
| Floor Mat | | Sun Roof | | Alloy Wheels | Yes | Grill Guard | | Rear Wiper | |
| Rear Spoiler | | Stereo (FULL) | | Navi/TV | | CD Player | | Car MD | |
| AUX | | Spare Tire | | Spare Tire Case | | Puncture Repairing Kit | | Tool | |
| Jack | | Operators Manual | | Maint. Record | | 360 Degree Camera | | AM/FM Radio | Yes |
| 4WD | Yes | 2WD | | Back Tire | | TV | Yes | Body Kit | |
| Side Skirts | | Front Lip Spoiler | | Turbo | | Side Airbag | | Wheel Spanner | |
| ESC | | Keyless Entry | | | | | | | |